


**INSPECTION REPORT
CO-OP / FISHERMAN'S WHARF
NEW BEDFORD WATERFRONT
FACILITIES INSPECTIONS
NEW BEDFORD, MASSACHUSETTS**



MARCH 2009

EXECUTIVE SUMMARY

Fisherman's Wharf is a filled pier structure retained by steel sheet piling. The wharf is currently protected by a timber fendering system and provides operational berthage for fishing vessels

Pare Corporation and Childs Engineering Corporation conducted the inspection of the site on November 13, 2008. In general, Fisherman's Wharf was found to be in **Good** condition overall. Concerns and deficiencies at the site include corrosion of the steel sheetpile bulkhead, damaged and corroded access ladders, and wearing of the timber fender system.

High priority repairs include the repair of the fendering system and ladders. The opinion of probable cost for this work is in the order of \$175,680.

Lower priority repairs include the addition of a cathodic protection system, which will increase the remaining useful life of the facility. The opinion of probable cost for this work is in the order of \$192,120.

It is recommended that the facility be inspected at 3 to 5 year intervals to monitor deterioration of the facility components.



TABLE OF CONTENTS

| | <u>Page</u> |
|---|-------------|
| SECTION 1 INTRODUCTION | |
| 1.1 Background and Objectives | 1 |
| 1.2 Scope of Work | 1 |
| SECTION 2 DESCRIPTION OF SITE | |
| 2.1 Site Location | 1 |
| 2.2 Facility Description | 1 |
| SECTION 3 EXISTING CONDITIONS | |
| 3.1 Observed Conditions – Topside | 2 |
| 3.2 Observed Conditions – Underwater | 2 |
| 3.3 Structural Condition Assessment | 2 |
| SECTION 4 STRUCTURAL CONDITION ASSESSMENT | |
| 4.1 Observed Conditions – Topside | 3 |
| 4.2 Observed Conditions – Underwater | 3 |
| SECTION 5 RECOMMENDATIONS AND OPINION OF PROBABLE COST | |
| 5.1 Recommendations – General | 8 |
| 5.2 High Priority | 8 |
| 5.3 Lower Priority | 8 |

FIGURES:

- Figure 1 – Locus Plan
- Figure 2 – Existing Site Plan
- Figure 3 – Existing Section and Elevation

TABLES:

- Table 3.1 – Observed Rub Rail Deficiencies
- Table 3.2 – Significant Underwater Conditions
- Table 3.3 – Underwater Readings
- Table 3.4 – Remaining Sheetpile Thickness

APPENDICES:

- Appendix A: Photographs
- Appendix B: Key Personnel
- Appendix C: Backup Data for Cost Estimates
- Appendix D: References
- Appendix E: Field Notes



Section 1 - Introduction

1.1 – Background and Objectives

The New Bedford Harbor Development Commission (HDC) has retained Pare Corporation (PARE) and Childs Engineering Corporation (CEC) to perform an above and below water inspection, and to develop a report of existing conditions for the Fisherman's Wharf in New Bedford, Massachusetts. Inspections were performed in accordance with the ASCE Manuals and Reports on Engineering Practice No. 101 – *Underwater Investigations: Standard Practice Manual*. The major objectives of the inspection report are to provide the HDC with an assessment of the existing conditions of the facility, and to substantiate requests for funding for the maintenance and repair of the facility.

1.2 – Scope of Work

The scope of this investigation is to provide an inspection and evaluation of the present condition of the wharf and appurtenant structures, and to provide information that will assist in both prioritizing repair needs and planning/conducting maintenance and operation.

The investigation is divided into three parts: 1) provide a description of the facility, including a review of available reports, investigations, and data previously submitted to the owner pertaining to the wharf and appurtenant structures; 2) perform a visual inspection of the site above and below water; 3) prepare and submit a final report presenting the evaluation of the structure, including recommendations for remedial actions, and associated opinions of probable cost.

Section 2 – Description of Site

2.1 - Site Location

Fisherman's Wharf a.k.a. Co-op Wharf is an approximate 1,121 foot long steel sheet pile bulkhead with solid fill. It is located north of the state pier along the New Bedford waterfront on New Bedford Harbor as shown in Figure 1 – Locus Plan.

2.2 - Facility Description

Fisherman's Wharf has been used for the docking of vessels since the 1800s. The original structure consisted of two filled piers, formerly known as City Pier #3 and City Pier #4, and was mainly used for the berthing of whaling vessels.

At present, Fisherman's Wharf is comprised of a PZ-38 steel sheet pile bulkhead, approximately 20 to 30 feet high, with solid fill. An interior steel wale and tieback



system provides the necessary lateral support for the wall. The pier provides docking space for modern fishing draggers and scallopers.

The bulkhead is protected with a timber fender system comprised of 10 inch x 10 inch vertical fenders spaced approximately 9.5 feet on center with a 3 inch x 8 inch UHMW rub rail bolted to the waterside face, with 8 inch x 10 inch timber chocks. The top of the steel sheeting is provided with a 3 inch x 12 inch cap channel. On top of the cap channel, an 8 inch x 12 inch timber curb is supported on 3 inch x 3 inch x 12 inch timber blocking spaced 36 inch on center. Docking cleats are 32 inch long and spaced approximately 28 feet on center, bolted to a concrete block measuring 54 inch long, 16 inch wide, and 12 inch high. The wharf supports an asphalt deck, primarily used for parking and access, with approximately 134 parking spaces available.

Original construction drawings for the facility have not been located at the time of this writing. According to available plans, the most recent repairs to the structure were completed in 1998. The repairs included the replacement of the original timber fender system with the current fendering, installation of fender pile clusters at the corners of the wharf, replacement of the steel sheet pile cap channel, removal of the original cathodic protection, and various repairs to the bituminous deck surface. These repairs did not include the area from Station 8+80 to Station 10+21.

Section 3 – Existing Conditions

3.1 - Observed Conditions – Topside

The topside and underwater inspections of the Fishermen's Wharf were performed on November 13, 2008. For reference purposes, a baseline was established along the top of the bulkhead during the inspection. Station 0+00 was located at the northwest corner of the bulkhead and extended to station 11+21 at the southern end of the bulkhead at its intersection with the State Pier. Observations were made in relation to their location along the baseline as appropriate and as noted herein. Reports of underwater conditions utilize the same baseline.

The timber vertical fenders were observed to be in overall good to fair condition, with the exception of several areas that were observed to be in poor condition. Typical deficiencies consist of rotting of the timber, wearing of the tops of fenders and fender faces, and impact damage causing splintering and splitting. A majority of the UHMW rub rails were observed to be missing or loose. Typically, the square top edge of the UHMW rub rail was observed to get caught on the rub rail on the docking vessels, causing them to be snagged and dislodged. The table below indicates specific locations of missing and loose rub rails.



Table 3.1 – Observed Rub Rail Deficiencies

| Location | Station | Deficiency | Condition |
|----------|-------------|---------------|-----------------|
| Topside | 0+50 | UHMW Rub Rail | Missing |
| Topside | 0+69 - 1+89 | UHMW Rub Rail | (14) Missing |
| Topside | 1+98 | UHMW Rub Rail | Loose |
| Topside | 1+98 - 4+12 | UHMW Rub Rail | (25) Missing |
| Topside | 4+30 | UHMW Rub Rail | Missing |
| Topside | 4+48 | UHMW Rub Rail | Missing |
| Topside | 4+65 | UHMW Rub Rail | Missing |
| Topside | 4+76 | UHMW Rub Rail | Loose |
| Topside | 4+85 - 5+05 | UHMW Rub Rail | (3) Missing |
| Topside | 5+23 - 5+88 | UHMW Rub Rail | (8) Missing |
| Topside | 6+23 - 6+61 | UHMW Rub Rail | (5) Missing |
| Topside | 6+70 | UHMW Rub Rail | Loose |
| Topside | 6+79 | UHMW Rub Rail | Missing |
| Topside | 6+88 | UHMW Rub Rail | Loose |
| Topside | 7+15 | UHMW Rub Rail | Loose |
| Topside | 7+24 - 7+82 | UHMW Rub Rail | (7) Missing |
| Topside | 8+00 | UHMW Rub Rail | Loose |
| Topside | 8+09 - 8+36 | UHMW Rub Rail | (4) Missing |
| Topside | 8+45 | UHMW Rub Rail | Broken top half |

From Station 0+00 to Station 3+25, the vertical fenders and chocks were observed to be in good condition with missing UHMW rub rails and minor wear of the vertical fenders. From Station 3+25 to Station 5+09 at the corner of the wall, the vertical fenders and chocks were observed to be in fair to poor condition. Several of the vertical fenders had significant wear at the top of the pile and along the fender face, the timber chocks were worn and splintered, and a majority of the UHMW rub rails were missing or loose. Also, the vertical fender at Station 4+76 was observed to be loose. The timber vertical fenders and chocks from Station 5+09 to Station 5+48 were observed to be in good to fair condition with minor wear observed along fender faces. From Station 5+48 to Station 5+75, the timber fender system was observed to be in fair to poor condition. The vertical fender at Station 5+51 is in poor condition and has been spilt vertically. The chocks and vertical fenders in this area are significantly worn and splintered. From Station 5+75 to Station 6+25, the timber chocks and vertical fenders were in good to fair condition. The timber vertical fenders and chocks from Station 6+25 to 7+00 were observed to be in fair to poor condition due to wear and impact damage. From Station 7+00 to Station 8+80, the fender system was observed to be in good condition. The docked vessel in this area utilized extra rubber fenders protecting both the vessel and fender system.

At Station 8+80, the fender system transitioned to an older fender system. The older fender system protects the steel sheetpile bulkhead from Station 8+80 to Station 10+44. It is comprised of 10 inch by 10 inch timber vertical fenders at 10 feet on center with 10 inch by 10 inch timber chocks. An 8 inch by 12 inch timber curb is supported by 3 inch by 12 inch by 12 inch blocks spaced 36 inch on center. The cleats in this area are 32 inch long and are bolted to either the cap channel or a welded steel box on top of the cap



channel. From Station 8+80 to Station 9+30, the vertical fenders and chocks are in fair condition with some signs of rot and wearing on faces. The timber curb was observed to be in poor condition with significant rot from Station 8+85 to Station 9+00. The timber chocks and vertical fenders were observed to be in fair to poor condition primarily because of wear from Station 9+30 to Station 9+80. From Station 9+80 to Station 10+44, the fender system appeared to be in good to fair condition. The older fender system terminates at Station 10+44 at the corner of the timber deck.

A 16 foot wide timber deck exists from Station 10+44 to Station 11+21 and was observed to be in overall good to fair condition. The timber decking was solid, with no loose boards noted. Some splintering and warping was observed. An existing railroad switch protruded through the deck at Station 10+95. From Station 10+06 to Station 10+44 and from Station 10+51 to Station 11+21, steel bollards with chain are mounted on top of the timber curb. Two gangways extend from the timber deck to floating docks. At Station 10+48 a 30 feet long aluminum gangway with 3.5 feet clear spacing was observed to be in good condition. At Station 11+09, a smaller 15 feet long aluminum gangway with 30 inch clear spacing extended to a floating barge and was observed to be in good to fair condition. Access to this gangway was restricted with the chain connecting two adjacent bollards.

Galvanized steel ladders are located at approximate 100 foot intervals around the bulkhead to provide access to and from the deck to the water below. Overall the ladders were observed to be in fair condition. Some of the ladders are in good condition above mean high water, while others have been damaged during impact with vessels causing damage to the rungs and buckling of the upright members. All of the ladders were observed to be corroded below mean high water rendering them unusable during times of low water.

Several areas of local subsidence were observed behind the bulkhead. At Station 1+05, a 12 inch long by 3 inch wide by 3 inch deep area of subsidence was observed with a loss of fill soils and asphalt. At Station 9+00, a 16 inch long by 6 inch wide by 1 inch deep area of subsidence was observed behind the bulkhead. A 24 inch long by 8 inch wide by 6 inch deep area of subsidence was observed at Station 9+34 with a loss of fill material and asphalt, as shown in Photo No. 18 in Appendix A - Photographs.

Life rings were observed along the bulkhead, spaced approximately 100 feet on center with a 4 inch x 4 inch post notched into the timber curb. The first life ring was observed at Station 0+16 and the final life ring positioned at Station 8+15. An emergency life boat was observed atop a steel frame from Station 0+95 and Station 1+21.

A list of all fenders, cleats, and life ring locations as well as any other deficiencies observed during the topside inspection is provided in Appendix E: Field Notes.



3.2 – Observed Conditions – Underwater

The underwater component of the underwater inspection of Fisherman's Wharf was performed by Childs Engineering Corporation on November 13, 2008. For reference purposes, the baseline that was established for the topside inspections also served as a baseline for the underwater inspection. The baseline follows the top of the bulkhead with Station 0+00 located at the northwest corner of the bulkhead extending to station 11+21 at the southern end of the bulkhead at its intersection with State Pier.

At Fisherman's Wharf, access was limited within the first 5 feet below the water line, as the vessels were docked tight to the wall with only 12 inches of timber fender separating them from the steel. Divers swam below the docked vessels and viewed elements that could be accessed safely.

Typically, at Fisherman's Wharf, the steel sheetpile bulkhead was observed to be actively corroding; however there is still significant steel section remaining. The existing coating is failing and there is a layer of black corrosion byproduct built up below the thin layer of marine growth. Corrosion has started to open up holes that were originally drilled through the sheeting for a bolted connection. The holes are typically located at about the MLW elevation. No anodes were found on the wall, consistent with a repair plan dated 1998 which indicates that anodes were to be removed from the wall at that time. The galvanized ladders are severely corroded at the bottom, with the bottom 3 rungs typically unusable. The timber fender system is in fair condition below the waterline. The timber is hard and sound and has some minor abrasion loss. There are some loose connections and missing sections because of corroded hardware. The following table indicates deficiencies observed during the underwater inspection.

Table 3.2 – Significant Underwater Conditions

| Location | Station | Deficiency | Description |
|------------|-------------|--------------------|---|
| Underwater | 0+05 | Ladder | Severely corroded |
| Underwater | 0+20 - 0+30 | Lower Wale | Fastening studs broken |
| Underwater | 0+40 - 1+73 | Lower Wale | Missing lower wale |
| Topside | 1+05 | Bituminous Deck | Local subsidence (3" x 12" x 5" deep) |
| Underwater | 1+42 | Vertical fender | Loose vertical fender Broken vertical fender |
| Underwater | 1+55 | Vertical fender | fender |
| Underwater | 1+67 | Ladder | No rungs below water; no connection |
| Underwater | 1+72.5 | Timber Dolphin | S.S. wire rope loose |
| Underwater | 2+00 | Sheetpile Bulkhead | 1.5" hole with bolt 1' below wale |
| Underwater | 2+54 - 2+80 | Lower Wale | Missing lower wale |
| Underwater | 2+53 | Vertical fender | Loose vertical fender |
| Underwater | 2+72 | Vertical fender | Loose vertical fender |
| Underwater | 4+15 | Ladder | No rungs below water |
| Underwater | 4+15 - 5+98 | Lower Wale | Missing lower wale |
| Underwater | 4+75 | Vertical fender | Loose vertical fender |
| Underwater | 4+84 | Vertical fender | Loose vertical fender |



| | | | |
|------------|---------------|--------------------|--|
| Underwater | 4+93 | Vertical fender | Loose vertical fender |
| Underwater | 5+02 | Sheetpile Bulkhead | 1.5" hole (backfill exposed) at lower wale |
| Topside | 5+04 | Steel Cap Channel | 3" hole in top of cap channel |
| Underwater | 5+08 | Timber Dolphin | Lower S.S. wire rope wraps loose (2 wraps) |
| Underwater | 5+27 | Vertical fender | Loose vertical fender |
| Underwater | 5+50 | Vertical fender | Loose vertical fender |
| Underwater | 6+50 - 7+50 | Lower Wale | Missing lower wale |
| Underwater | 6+98 | Ladder | Severely corroded |
| Underwater | 7+98 - 8+08 | Lower Wale | Missing lower wale |
| Underwater | 8+27 - 8+37 | Lower Wale | Missing lower wale |
| Underwater | 9+05 | Lower Wale | Rotting timber, hollow |
| Underwater | 9+14 | Lower Wale | Rotting timber, hollow |
| Underwater | 9+16 | Lower Wale | 4" diam. bolt hole |
| Topside | 9+34 | Bituminous Deck | Local subsidence (8" x 24" x 6" deep) |
| Underwater | 9+58 - 9+75 | Lower Wale | Marine borer - 50% section loss |
| Underwater | 9+85 - 9+87 | Lower Wale | Marine borer - Hollow end section |
| Underwater | 10+44 - 11+21 | Sheetpile Bulkhead | 1.5" holes in outer flange (backfill exposed) 5' below top of wall |
| Underwater | 10+39 - 10+44 | Corner of wall | Loose and hanging wale |

During the inspection of the sheetpile, ultrasonic thickness (UT) and cathodic potential (CP) reading were taken. The readings were taken at the mudline, mean low water, and approximately halfway between the two. There was a large sheen of oil surrounding this structure that prevented the dive inspection team from obtaining meaningful potential readings. While passing the silver-silver chloride cell through this oil sheen the cell was contaminated and it was not reading correctly on the voltage meter. Conditions at this facility were found to be similar to adjacent facilities such as the Steamship Pier, Homer's Wharf, and Leonard's Wharf which all indicated potential readings between .3 and .5 volts. The following table illustrates the results.

Table 3.3 – Underwater Readings

| STATION | ELEVATION | UT | UT | UT | CP |
|---------|-----------|--------------|-------|--------------|------------|
| | | Inner Flange | Web | Outer Flange | |
| 0+00 | Mud | 0.525 | 0.345 | 0.535 | ERR |
| | Mid | 0.485 | 0.280 | 0.485 | ERR |
| | MLW | 0.525 | 0.315 | 0.495 | ERR |
| 2+00 | Mud | 0.520 | 0.385 | 0.510 | no reading |
| | Mid | 0.505 | 0.360 | 0.500 | ERR |
| | MLW | 0.490 | 0.295 | 0.470 | ERR |
| 4+00 | Mud | 0.540 | 0.335 | 0.520 | no reading |
| | Mid | 0.535 | 0.345 | 0.505 | ERR |
| | MLW | 0.505 | 0.365 | 0.500 | ERR |
| 6+00 | Mud | 0.545 | 0.370 | 0.525 | |
| | Mid | 0.530 | 0.355 | 0.505 | 0.500 |
| | MLW | 0.510 | 0.340 | 0.460 | 0.500 |
| 8+00 | Mud | 0.550 | 0.385 | 0.525 | 0.663 |
| | Mid | 0.545 | 0.370 | 0.565 | ERR |
| | MLW | 0.550 | 0.370 | 0.525 | 0.602 |



| | | | | | |
|-------|-------------------|-------|-------|-------|------------|
| 10+00 | Mud Mid MLW | 0.520 | 0.335 | 0.515 | no reading |
| 11+21 | Mud Mid MLW | 0.510 | 0.370 | 0.505 | |

Section 4 – Structural Condition Assessment

4.1 – Structural Condition Assessment

Based on the observations obtained from the site inspections, the following provides our assessment of the various structural components. Existing structure conditions were based on visual and tactile observations only, and were limited to accessible and visible portions of the structures.

Based upon the visual inspection of topside and underwater structures along with the observed thickness readings, Fisherman's Wharf is considered to be in generally good condition. Corrosion along the flanges of the steel sheetpile bulkhead sections was observed to be minimal, with greater loss of section observed in the web areas. The following table represents the thickness readings and estimated remaining section steel sheetpile.

Table 3.4 – Remaining Steel Sheetpile Thickness

| Nominal Flange Thickness = 0.500" | | | Nominal Web Thickness = 0.375" | | |
|-----------------------------------|-------------------|-------|--------------------------------|--------------|-------------------|
| Inner Flange | Percent Remaining | Web | Percent Remaining | Outer Flange | Percent Remaining |
| 0.525 | 105.0 | 0.345 | 92.0 | 0.535 | 107.0 |
| 0.485 | 97.0 | 0.280 | 74.7 | 0.485 | 97.0 |
| 0.525 | 105.0 | 0.315 | 84.0 | 0.495 | 99.0 |
| 0.520 | 104.0 | 0.385 | 102.7 | 0.510 | 102.0 |
| 0.505 | 101.0 | 0.360 | 96.0 | 0.500 | 100.0 |
| 0.490 | 98.0 | 0.295 | 78.7 | 0.470 | 94.0 |
| 0.540 | 108.0 | 0.335 | 89.3 | 0.520 | 104.0 |
| 0.535 | 107.0 | 0.345 | 92.0 | 0.505 | 101.0 |
| 0.505 | 101.0 | 0.365 | 97.3 | 0.500 | 100.0 |
| 0.545 | 109.0 | 0.370 | 98.7 | 0.525 | 105.0 |
| 0.530 | 106.0 | 0.355 | 94.7 | 0.505 | 101.0 |
| 0.510 | 102.0 | 0.340 | 90.7 | 0.460 | 92.0 |
| 0.550 | 110.0 | 0.385 | 102.7 | 0.525 | 105.0 |
| 0.545 | 109.0 | 0.370 | 98.7 | 0.565 | 113.0 |
| 0.550 | 110.0 | 0.370 | 98.7 | 0.525 | 105.0 |
| 0.520 | 104.0 | 0.335 | 89.3 | 0.515 | 103.0 |
| 0.520 | 104.0 | 0.340 | 90.7 | 0.510 | 102.0 |
| 0.510 | 102.0 | 0.370 | 98.7 | 0.505 | 101.0 |



Typical UT readings on both the web and flanges displayed reduced thicknesses near mean low water, however the amount of section loss is considered to be minor. Thickness readings on the web indicated average section loss of 7.3% with a maximum reading of 22.3% loss. Using the average section loss and estimating the construction date to 1975, average corrosion rates cause a loss of section of approximately 0.001 inch per year or 0.2%. The minimum thickness reading indicates a section loss of 0.095 inch or 25.3%, corresponding to a maximum section loss of 0.003 inch per year or 0.75%.

Although the coating has played an important role in the corrosion protection of the sheeting, corrosion rates will accelerate if the sheeting is left untreated. Based upon average corrosion rates in the area, if left untreated, the expected life of the sheeting is anticipated to be in the order of 25 years. The installation of coatings and cathodic protection can increase this remaining useful life.

Section 5 - Recommendations and Opinion of Probable Cost

5.1 – Recommendations - General

Based on conditions observed during the inspections, and the corresponding assessments of the existing structures, the following recommendations are provided for the repair and rehabilitation of this facility. Existing structure conditions and assessments were based on visual and tactile observations only, and were limited to accessible and visible portions of the structures.

Opinions of probable cost were generated based upon current industry unit prices for similar work. Breakdowns of cost are provided in the Appendix. The opinions provided are for construction only and do not include allowances for engineering, permitting, or construction administration. A 20 percent contingency has been included with these costs. The opinions shown herein are based on a limited investigation and are provided for general information only. This should not be considered an engineer's estimate, as actual construction costs may be somewhat less or considerably more than indicated, due to fluctuations in the market and the actual repair implemented.

5.2 – High Priority

The following items are considered to have a Medium to High Priority, as they affect the usability and safety of the structure:

A. Repair and Rehabilitate the Existing Timber Fender System

This item consists of the removal and replacement of damaged, missing and excessively worn components of the timber fender system. This item also includes the replacement of the older fender system from Station 8+80 to 10+44,



which was not rehabilitated in 1998. The opinion of probable construction cost is approximately \$62,400.

The opinion of probable construction cost to rehabilitate the older section of the existing timber fender system from Station 8+80 to 10+44 is approximately \$41,280.

B. Remove and Replace Access Ladders

This item consists of the removal and replacement of damaged and deteriorated ladders. Also included in this item is the removal of the remaining UHMW facing. The opinion of probable construction cost is approximately \$24,000.

5.3 – Lower Priority

The following items are considered to have a Lower Priority, as they presently do not affect the usability and safety of the structure, but will need to be addressed in approximately 5 to 10 years.

A. Install Cathodic Protection System

This item consists of the installation of a new aluminum anode cathodic protection system, welded to the existing steel sheet piling below mean low water. The cathodic protection system will inhibit steel section loss due to corrosion below the water line. The opinion of probable construction cost is approximately \$146,100.



Figures
Fisherman's Wharf
New Bedford, Massachusetts



0 1000 FEET 0 1/2 500m 1000m
 1 MILE
 Printed from TOPOI ©1999 Wildflower Productions (www.topo.com)





FISHERMAN'S WHARF
NEW BEDFORD, MASSACHUSETTS
 NEW BEDFORD HARBOR DEVELOPMENT COMMISSION
 NEW BEDFORD WATERFRONT FACILITY INSPECTIONS
 NOVEMBER 2008

FIGURE 1
LOCUS PLAN

NEW BEDFORD WATERFRONT FACILITIES INSPECTIONS
FISHERMAN'S WHARF
 NEW BEDFORD HARBOR DEVELOPMENT COMMISSION
 NEW BEDFORD, MASSACHUSETTS

MACARTHUR DRIVE




- NOTES:**
1. CONDITIONS INSPECTION PERFORMED BY PARE PERSONEL ON NOVEMBER 13, 2008.
 2. UNDERWATER CONDITION INSPECTION PERFORMED BY CHILDS ENGINEERING CORP. ON NOVEMBER 13, 2008.
 3. SITE PLAN BASED UPON DRAWING ENTITLED "PLAN VIEW FISHERMAN'S WHARF" BY TIBBETTS ENGINEERING CORP. DATED JAN. 23, 1998, AND CONDITIONS OBSERVED DURING THE INSPECTION.

EXISTING SITE PLAN
 SCALE 1"=20'


| REVISIONS: | |
|------------|--|
| | |
| | |
| | |
| | |
| | |

PROJECT NO.: 08216.00
 DATE: NOVEMBER 2008
 SCALE: AS NOTED
 DESIGNED BY: -
 CHECKED BY: -
 DRAWN BY: RMM
 APPROVED BY: KWH
 DRAWING TITLE:


HALF SIZED



TIMBER FENDER ELEVATION
SCALE: 1"=4'



TIMBER FENDER PLAN VIEW
SCALE: 1"=4'



SHEETPILE BULKHEAD AND FENDER SECTION
SCALE: 1"=4'



**NEW BEDFORD WATERFRONT
FACILITIES INSPECTIONS
FISHERMAN'S WHARF**
NEW BEDFORD HARBOR DEVELOPMENT COMMISSION
NEW BEDFORD, MASSACHUSETTS

**EXISTING SECTION
AND ELEVATION**

DRAWN BY:
RMM
CHECKED BY:
KWH
APPROVED BY:
KWH

DATE:
NOVEMBER 2008
PROJECT NO.:
08216.00
SCALE:
AS NOTED

FIGURE NO.:
3
SHEET NO.:
1 OF 1

Appendix A
Photographs
Fisherman's Wharf
New Bedford, Massachusetts



Photo No. 1: Overview of the Fisherman's Wharf.



Photo No. 2: Steel Sheetpile bulkhead from approximately Station 0+20 to Station 1+73.



Photo No. 3: Typical overview of the timber fender system with UHMW rubber rails.



Photo No. 4: Emergency Life Boat from Station 0+95 to Station 1+21.



Photo No. 5: Typical worn fender pile with missing UHMW rub rail.



Photo No. 6: Typical loose UHMW rub rail.




Photo No. 7: Overview of the Wharf and fender system from Station 5+09 looking northwest.



Photo No. 8: Worn fender pile in contact with a docked vessel.



Photo No. 9: Overview of the eastern corner of the wharf.




Photo No. 10: Top of a splintered and broken fender pile.



Photo No. 11: Typical access ladder with corroded rungs.



Photo No. 12: Overview of the older fender system from Station 8+84 to Station 10+44.



Photo No. 13: Older fender system with rotted timber curb and damaged chocks.



Photo No. 14: Overview of the steel sheetpile bulkhead beneath the timber deck from Station 10+44 to Station 11+21.



Photo No. 15: Overview of the timber deck from Station 10+44 to Station 11+21.



Photo No. 16: Overview of the timber curb with steel bollards along the timber deck.



Photo No. 17: Subsidence behind the steel sheetpile bulkhead at Station 1+06.



Photo No. 18: Subsidence behind the steel sheetpile bulkhead at Station 9+34.



Photo No. 19: Observed steel sheetpile condition underwater (Photo by Childs Engineering Corp.)




Photo No. 20: Observed steel sheetpile condition underwater (Photo by Childs Engineering Corp.)




Photo No. 21: Observed steel sheetpile condition underwater (Photo by Childs Engineering Corp.)




Photo No. 22: Observed steel sheetpile condition underwater (Photo by Childs Engineering Corp.)




Photo No. 23: Observed steel sheetpile condition underwater (Photo by Childs Engineering Corp.)




Photo No. 24: Observed steel sheetpile condition underwater (Photo by Childs Engineering Corp.)

Appendix B
Key Personnel
Fisherman's Wharf
New Bedford, Massachusetts

KEY PERSONNEL

The following personnel were involved with this project including but not limited to the topside and underwater inspections and the preparation of this report:

| Name | Employer | Responsibilities |
|-------------------------------|--------------------------------|---|
| Karl Hammond, P.E. | PARE Corporation | Project Manager, Lead Engineer |
| Ernest O. Rabideau, Jr., P.E. | PARE Corporation | Project Reviewer |
| Matt Bellisle, P.E. | PARE Corporation | Principal in Charge |
| Craig Sams, P.E. | Childs Engineering Corporation | Principal in Charge |
| Robert Garrity, P.E. | Childs Engineering Corporation | Project Engineer for Underwater Inspections |
| Kevin Champagne, P.E. | PARE Corporation | Support Engineer |
| Richard Fitzgerald, P.E. | Childs Engineering Corporation | Underwater Inspection Team |
| Charlie Marshall Roberts | Childs Engineering Corporation | Underwater Inspection Team |
| Robert Welch | Childs Engineering Corporation | Underwater Inspection Team |
| Phil Iantosca | Childs Engineering Corporation | Underwater Inspection Team |
| Nicholas B. Sarata | Childs Engineering Corporation | Underwater Inspection Team |
| Ryan McCoy | PARE Corporation | Topside Inspection |
| Briscoe B. Lang | PARE Corporation | Permitting Services |



Appendix C
Backup Data for Cost Estimates
Fisherman's Wharf
New Bedford, Massachusetts

FISHERMENT'S WHARF
OPINION OF PROBABLE CONSTRUCTION COST
February, 2009

| WHARF REHABILITATION | | | | |
|-----------------------------|-----|------|------------|-------|
| | QTY | UNIT | UNIT PRICE | TOTAL |

High Priority Repairs

| | | | | |
|-------------------------------------|-------|-------|--------------|---------------|
| 1. Mobilization/Demobilization | 1 | LS | \$ 10,000.00 | \$ 10,000.00 |
| 2. Demolition and Removal | 1 | LS | \$ 8,000.00 | \$ 8,000.00 |
| 3. Replace Timber Fenders | 8,700 | Bd.Ft | \$ 12.00 | \$ 104,400.00 |
| 4. Ladders and Miscellaneous Timber | 1 | LS | \$ 24,000.00 | \$ 24,000.00 |

| | | | |
|--|--------------------|-----------|-------------------|
| | Subtotal | \$ | 146,400.00 |
| | Contingency 20% | \$ | 29,280.00 |
| | Total Alt.1 | \$ | 175,680.00 |

Low Priority Repairs

| | | | | |
|--------------------------------|--------|----|--------------|---------------|
| 1. Mobilization/Demobilization | 1 | LS | \$ 10,000.00 | \$ 10,000.00 |
| 2. Demolition and Removal | 1 | LS | \$ 4,000.00 | \$ 4,000.00 |
| 3. Install Cathodic Protection | 12,175 | LB | \$ 12.00 | \$ 146,100.00 |

| | | | |
|--|--------------------|-----------|-------------------|
| | Subtotal | \$ | 160,100.00 |
| | Contingency 20% | \$ | 32,020.00 |
| | Total Alt.2 | \$ | 192,120.00 |



Appendix D
References
Fisherman's Wharf
New Bedford, Massachusetts

REFERENCES

The following references were utilized during the preparation of this report and the development of the recommendations presented herein:

1. "About the Port – Key Locations", New Bedford Harbor Development Commission, <http://www.newbedford-ma.gov/PortofNewBedford/AboutPort/KeyLocations.html>
2. Construction Drawings "Proposed Repairs and Improvements to Wharves and Piers in New Bedford and Fairhaven, MA", Tibbetts Engineering Corp., January 23, 1998 (Revised March 20, 1998).



Appendix E
Field Notes
Fisherman's Wharf
New Bedford, Massachusetts

Nov. 13, 08
45°F

FISHERMAN'S WHARF

N.B. WATERFRONT INSPECTIONS OVERCAST

STA 0+3.0 - 36" CLEAT 16x55x11"
CONCRETE BLOCK
(2) 7/8" BOLTS

0+3.7 - FENDER (P)

0+5.7 - START OF CURB
→ 8" X 12" TIMBER CURB
→ 3" X 8" X 12" BULKHEAD 36" OC

0+12.8 - FENDER (P)

0+16.0 - LIFE RING

0+22.0 - FENDER (P)

0+31.0 - CLEAT / FENDER (P)

0+40.5 - FENDER (P)

0+49.8 - FENDER (M)

0+59.0 - CLEAT / FENDER (P)

0+68.5 - FENDER (M)

0+77.8 - FENDER (M)

0+87.0 - CLEAT / FENDER (M)

0+94.0 - LADDER (BUCKLED) 18" CLEAR
7" CHANNEL

0+95.0 - LIFE RAFT FRAME

0+96.0 - FENDER (M)

1+05.5 → FENDER (M)
- LOCAL SUBSIDENCE (3" X 12" ASD)

- * UHMW PULLED OFF BY BOAT RUB RAIL
- * 10" X 10" FENDERPILES * 8" X 10" CHOCKS
- * P = PRESENT UHMW
- * M = MISSING UHMW
- * 3" X 12" CAP CHANNEL

| WATER | DEPTH | TO | TOP OF | DELTA |
|-------|---------|----|--------|-------|
| | → 16' | @ | STA | 0+25 |
| | → 19' | @ | STA | 0+50 |
| | → 21.5' | @ | STA | 0+75 |
| | → 19' | @ | STA | 1+00 |
| | → 21.5' | @ | STA | 1+25 |
| | → 23' | @ | STA | 1+50 |
| | → 27.5' | @ | STA | 1+75 |
| | → 25.5' | @ | STA | 2+00 |
| | → 24' | @ | STA | 2+25 |
| | → 25' | @ | STA | 2+50 |
| | → 26' | @ | STA | 2+75 |
| | → 24.5' | @ | STA | 3+00 |
| | → 25' | @ | STA | 3+25 |
| | → 23' | @ | STA | 3+50 |
| | → 26' | @ | STA | 3+75 |
| | → 29' | @ | STA | 4+00 |
| | → 30.5' | @ | STA | 4+25 |
| | → 28.5' | @ | STA | 4+50 |
| | → 26' | @ | STA | 4+75 |
| | → 29' | @ | STA | 5+00 |
| | → 28.5' | @ | STA | 5+25 |
| | → 27.5' | @ | STA | 5+75 |
| | → 26.5' | @ | STA | 6+00 |

③

- 1+14.5 - CLEAT/FENDER (M)
- 1+21.0 - LIFE BOAT FRAME
- 1+24.0 - FENDER (M)
- 1+33.0 - FENDER (M)
- FENDERS FAIR TO G-0015
SLIGHTLY WORN
- 1+42.5 - CLEAT/FENDER (M)
- 1+51.0 - SHORE POWER
- 1+52.0 - FENDER (M)
- 1+61.0 - FENDER (M)
- 1+65.0 - LADDER (BUKLED/RINGS S.P.)
- 1+70.0 - CLEAT/FENDER (M)
- 1+72.5 - CORNER OF WALL
-(7) TIMBER PILE CLUSTER
- 1+76.0 - CLEAT
- 1+79.5 - FENDER (M)
- 1+89.0 - FENDER (M)
- 1+92.0 - LIFE RING
- 1+98.0 - FENDER (P - LOOSE)
- 2+07.0 - CLEAT
- 2+23.5 - LADDER (FAIR COND) 10" HAND GRIP
- 2+38.0 - CLEAT

* TOPS OF FENDERS WORN
 * WILL NOTE UHMW PRESENCE (NOT MISSING)
 * FENDERS SPACED 9.5' O.C (TYP.)

④

| WATER DEPTH TO TOP OF | DECK |
|-----------------------|-----------|
| → 23.5' @ | STA 6+50 |
| → 23.5' @ | STA 6+75 |
| → 24' @ | STA 7+00 |
| → 20.5' @ | STA 7+25 |
| → 19' @ | STA 7+50 |
| → 19' @ | STA 7+75 |
| → 18.5' @ | STA 8+00 |
| → 17.5' @ | STA 8+25 |
| → 17.0' @ | STA 8+50 |
| → 17.0' @ | STA 8+75 |
| → 19.0' @ | STA 9+00 |
| → 18' @ | STA 9+25 |
| → 17' @ | STA 9+50 |
| → 17.5' @ | STA 9+75 |
| → 12' @ | STA 10+00 |
| → 10' @ | STA 10+25 |
| → 7' @ | STA 10+50 |
| → 10.5' @ | STA 10+75 |
| → 7.5' @ | STA 11+00 |

5

- 2+ 69.0 - CLEAT
- 3+ 00 - CLEAT
- 3+ 17.0 - LADDER (GOOD COND)
- 3+ 24.0 - CLEAT
- 3+ 48.0 - CLEAT
- 3+ 79.0 - CLEAT
- 3+ 95.0 - LIFE RING
- * FENDER TOPS / TOP CHOCKS WORN / SPRINT REED
- 4+ 11.0 - CLEAT
- 4+ 18.0 - LADDER (BUCKLED)
- 4+ 20.15 - FENDER (P)
- 4+ 39.0 - FENDER (P)
- 4+ 42.0 - CLEAT
- 4+ 57.0 - FENDER (P)
- 4+ 72.0 - CLEAT
- 4+ 76.0 - FENDER (P) * LOOSE
- 5+ 00 - END CURB
- 5+ 03 - CLEAT
- 5+ 09 - CORNER OF WALL
- 5+ 11.0 - (7) TIMBER PILE CLUSTER
- 5+ 30 LADDER (GOOD CONDITION)
- 5+ 41.0 - FENDER (P)

6

INSPECTION NOTES:

- 5+ 04 - HOLE IN TOP OF WALL
CAP CHANNEL ± 3" Ø
 - 5+ 48 - TOP CHOCKS AND FENDER
WORN (FAIR TO POOR) ± 25'
 - 6+ 25 - TOP CHOCKS AND FENDER
WORN (FAIR TO POOR) ± 25'
 - 7+ 00 - TOP CHOCKS AND FENDERS
IN 'GOOD TO FAIR COND
± 175' (BOAT USES TIRES
BETWEEN HULL & FENDER)
 - 8+ 80 - TRANSITION FROM NEW
FENDER SYSTEM TO OLD F.S.
 - 8+ 85 - TIMBER CURB IN POOR COND F/S
- * OLD FENDER SYSTEM: 8" X 12" TIMBER CURB
3" X 12" X 12" BLOCKS @ 36" O.C.
10" X 10" FENDERS @ 10' O.C., 10" X 10" CHOCKS

7

- 5+19.0 - START OF TIMBER CURB
- 5+48.0 - CLEAT
- 5+75.75 - CLEAT
- 5+96.0 - LADDER (MINOR BUCKLING)
- 5+97.5 - FENDER (P)
- 6+01.0 - CLEAT
- 6+04.5 - FENDER (P)
- 6+07 - LIFE RING
- 6+14.0 - FENDER (P)
- 6+28.5 - CLEAT
- 6+50.5 - FENDER PILE SPLIT VERT: ALL
- 6+57.0 - CLEAT
- 6+61.5 - FENDER (UNWATTACHED w/
1 BOLT + ROPE TO CURB)
- 6+84.5 - CLEAT
- 6+88.0 - FENDER (UNWATT. w/ 2 BOLTS)
- 6+95.0 - LADDER (GOOD CONDITION)
- 6+97.0 - FENDER (P)
- 7+07.0 - FENDER (P)
- 7+13.0 - CLEAT
- 7+15.0 - FENDER (UNWATT. w/ BOLTS + ROPE)
- 7+10.75 - CLEAT

8


| INSPECTION NOTES: | |
|---|---|
| 9+27-9+50 | OLD UTILITY PVC PIPE RUNS WATERSIDE OF CURB |
| 9+50-9+62 | PITTING OF STEEL WALL CAP CHANNEL |
| 9+40 | TOP CHOCKS AND FENDER PILES WORN (FAIR TO POOR) ± 40' |
| 10+05 | POSSIBLE LOCAL SUBSIDENCE ± 20' |
| 10+44 | 11+21 - 16' WIDE CANTILEVERED TIMBER DECK |
| 10+55 | (2) 6' WIDE BENCHES (TIMBER) |
| 10+95 | RR TRACK SWITCH THROUGH TIMBER DECK |
| * TIMBER DECK IN GOOD TO FAIR CONDITION SEVERAL LOOSE AND WARPED BOARDS | |

- 7+68.5 - CLEAT
- 7+88.0 - LADDER (GOOD CONDITION)
- 7+90.5 - FENDER (P)
- 7+96.0 - CLEAT
- 7+99.5 - FENDER (P - LOOSE)
- 8+14.5 - LIFE RING
- 8+23.5 - CLEAT
- 8+45 - FENDER (P - TOP HALF MISSING)
- 8+50.75 - CLEAT
- 8+54.0 - FENDER (P)
- 8+63.0 - FENDER (P)
- 8+72.0 - FENDER (P)
- 8+81.0 - CLEAT / FENDER (P)
- 8+84.0 - CORNER OF WALL
- 8+99.0 - LADDER
- 9+09.0 - CLEAT ATTACHED TO WALL CAP CHANNEL
- 9+15.0 - CORNER OF WALL
- 3 TIMBER PILE CLUSTER
- 9+19.0 - CLEAT (36" ATT. TO WELDED BOX)
- 9+34.0 - LOCAL SUBSIDENCE 24" X 8" W X 6" D
- HOLE IN ASPHALT
- 9+39.5 - CLEAT ATT. TO WALL CAP CHANNEL

* OLD FENDER SYSTEM STRUTS @ CORNER @ STA 8+84

* LOCAL SUBSIDENCE @ STA 9+00 16" X 6" W X 1" D

| DECK | INSTRUCTION | NOTES |
|----------|--------------------------------------|---------------------------------------|
| STA 0+25 | - O+50 | - PUDDLE MH |
| STA 0+95 | - 1+21 | - LIFE RAFT FRAME PROTECTED w/ BOARDS |
| STA 1+00 | - MH 20' | FROM TOW |
| STA 1+10 | - CB 20' | FROM TOW |
| | - DRAIN MH 10' | & 12' FROM TOW |
| STA 1+37 | - ELECTRIC BOX | 6' FROM TOW |
| STA 2+37 | - SEWER MH | ± 13' FROM TOW |
| STA 2+49 | - CB ± 15' | FROM TOW |
| | - DRAIN MH @ 10' | & 8' FROM TOW |
| | * ASPHALT PATCH @ CORNER OF ST 15' L | |
| STA 2+58 | - MH 20' | FROM TOW |
| STA 2+80 | - 15' FROM TOW | = ASPHALT PATCH ± 7' WIDE, 45' LONG |
| STA 6+10 | - SEWER MH 22' | FROM TOW |
| STA 6+20 | - CB 18' | FROM TOW |
| | - DRAIN MH 13' | & 8' FROM TOW |
| STA 6+15 | - 12" X 12" ASPHALT MISSING | |
| | ± 2' | FROM TOW |
| STA 6+33 | - MH ± 32' | FROM TOW |
| STA 6+60 | - ASPHALT PATCH | |




- 9+52-9+60 - GAP IN TIMBER CURB
- 9+70.5 - CLEAT ATT. TO WALL CAP CHANNEL
- 9+83.0 - CLEAT ATT. TO WALL CAP CHAW
- 9+91.5 - CLEAT ATT. TO WELDED BOX
- 10+06.0 - 10+11 - GAP IN TIMBER CURB
- 10.06.5 - STEEL BOLLARD (4" ϕ)
- 10+11 - BOND IN WALL
- 10+13 - STEEL BOLLARD (8" ϕ) TOP OF CURB
- 10+20.5 - STEEL BOLLARD (8" ϕ) CURB
- 10+24, 10+40, 10+86 - 40" WIDE SIGN
- 10+28.5 - STEEL BOLLARD (8" ϕ) CURB
- 10+36 - STEEL BOLLARD (8" ϕ) CURB
- 10+43.5 - ONE TIMBER CANTILEVER WHARF
- 10+44.5 - STEEL BOLLARD (8" ϕ) CURB
- 10+46.0 - 10+50.5 - GAP IN CURB
- ALUMINUM GANGWAY
- 3.5' CLEAR \pm 30' L
- 10+51.5 - STEEL BOLLARD (8" ϕ) CURB
- 10+52.5, 10+57.5, 10+62.5
- 5" X 5" X 9' TYP PVC POSTS
- 10+59.0 - STEEL BOLLARD (8" ϕ) CURB

* STEEL BOLLARDS 8' O.C. (TYP)

DECK INSPECTION NOTES

- STA 7+75 - CB 18' FROM TDW
- DRAIN MH 13' x 8' FROM TDW
- STA 7+88 - SEWER MH 20' FROM TDW
- STA 8+00 - MH 12' FROM TDW
- STA 8+85 - PAY PHONE BOOTH (VERIZON)
- STA 8+60 - ELECTRIC MH 45' FROM TDW
- STA 8+75 - TELEPHONE MH 45' FROM TDW



11/13/08

Every 100' cleaner
Every 200' measure

Co-op/Fishermans Wharf

| Station | Elevation | UT | | | CP |
|---------|-----------|--------------|-------|---------------|---------------------|
| | | Inner Flange | WEB | Outter Flange | |
| 0+00 | Mud | .525" | .345" | .535" | 120.1 - 79.4 |
| | Mid | .485" | .280 | .485 | 99.8 (73.4 - 127.0) |
| | MLW | .525" | .315 | .495 | 86.6 |
| 0+25 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 0+50 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 0+75 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 1+00 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 1+25 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 1+50 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 1+75 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 2+00 | Mud | .520" | .385" | .510" | No READING |
| | Mid | .505" | .360" | .500" | 109.4 |
| | MLW | .490" | .295" | .470" | 107.7 |
| 2+25 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 2+50 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 2+75 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 3+00 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 3+25 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |

readings in millivolts - note water covered no oil volume per silver silver chloride cell
 # readings in water if was getting covered no oil which interferes with proper reading

Co-op/Fishermans Wharf

| Station | Elevation | UT | | | CP |
|---------|-----------|--------------|-------|---------------|-----------------|
| | | Inner Flange | WEB | Outter Flange | |
| 3+50 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 3+75 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 4+00 | Mud | .540" | .335" | .520" | No READING 16.8 |
| | Mid | .535" | .345" | .505" | 12.5 |
| | MLW | .505" | .365" | .500" | 17.5 |
| 4+25 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 4+50 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 4+75 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 5+00 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 5+25 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 5+50 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 5+75 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 6+00 | Mud | .545" | .370" | .525" | |
| | Mid | .530" | .355" | .505" | .06-1.23 ✓ |
| | MLW | .510" | .340" | .400" | .773-1.119 ✓ |
| 6+25 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 6+50 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 6+75 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |

Co-op/Fishermans Wharf

| Station | Elevation | UT | | | CP |
|---------|-----------|--------------|-------|---------------|---------------|
| | | Inner Flange | WEB | Outter Flange | |
| 7+00 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 7+25 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 7+50 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 7+75 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 8+00 | Mud | .550" | .385" | .525" | .063-1.224 |
| | Mid | .545" | .370" | .505" | 1.277-.709 |
| | MLW | .550 | .370" | .525" | .602-1.062 |
| 8+25 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 8+50 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 8+75 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 9+00 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 9+25 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 9+50 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 9+75 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 10+00 | Mud | .520" | .335" | .515" | NO READINGS ✓ |
| | Mid | | | | |
| | MLW | .520" | .340" | .510" | |
| 10+25 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |

872-1.185
 Readings in
 10/14

Co-op/Fishermans Wharf

| Station | Elevation | UT | | | CP |
|-------------|-----------|--------------|-------|---------------|----|
| | | Inner Flange | WEB | Outter Flange | |
| 10+50 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 10+75 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 11+00 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 11+25 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 11+50 | Mud | | | | |
| | Mid | | | | |
| | MLW | | | | |
| 11+75 21 | Mud | | | | |
| | Mid | | | | |
| | MLW | .510" | .370" | .505" | |

11/13/08 New Bedford Harbor

POI, NBS, RPY

left office 6:20 AM
arrived site 7:30 AM

RGE - left 7:00 AM
arrive site 7:30 AM

met w/ U.S. Harbor personnel
Pave Eros.

Station Fisherman's Wharf
Set up dive equipment

Dive rig @ 9:45, start @ Sta 0+00.
visibility ~ 8'

4 blend by product
Surface many small pieces

halt diving 9:50 for base docking
for 5 minutes

Dive in @ 1530

@ Sta 11+21

Level III, 5.05 outside f1
3.70 web
5.10 inside f1

Sta 10+44 to 11+21 1 1/2" hole on 1 outside
entire length flange 5' from Top (middle)
backfill exposed

6'-7' of sheet piling exposed
from MLW to 3' above MLW

bulkhead has extension made
w/ tie rods.

Sta 10+78 6" ϕ conc pipe @ headwall
top of pipe 12" \pm below MLW

Conc hard, max $\frac{1}{8}$ " soft

Sta 10+37 to 10+44 @ corner
top fender being made loose
or hanging

Sta 9+15 - 10+44 (PDI Diver)
sheet piling not coated


PDI, NBS, RPI returned
to office at 6:30 pm on 11/13

11/14/08 PDI, NBS, RPI
to New Bedford at 6:30 AM
~~Boat~~
arrived at 7:20

11/14/08 RFG & RSW on site 7 am
Divers RSW 10:00 am
PDI 12:30 007
RFG Notes

Divers RSW 2:30 in
PDI 4:10 out

11/14/08 5:00 ~~6:30~~ 5:00 off site
1:00 Ride back to office





CHILDS ENGINEERING CORPORATION

Waterfront and Structural Engineering

BOX 333, MEDFIELD, MA 02052

JOB FISHERMAN'S WHARF N.B.

SHEET NO. 1 OF

CALCULATED BY RGF DATE 11/13/08

CHECKED BY DATE

SCALE

Sta 0+00 Diver in @ 9:45

visibility ≈ 8'

Steel - 1/4" corrosion by-product

@ ML surface wavy w/ small pitting 1/16" - 1/8" deep + diameter

No coating on steel

Steel above MLW looks good - w/ surface corrosion

ladder @ MLW severely corroded - located @ Sta - 0+05' ±

- small hole on outside of 1 @ mid height - 1 1/2" φ - steel thick on edges - may be bolt hole for fender.

- 0+05 - ^{fender} lower wale - 3' dia pipe - low wale cut for pipe
 interior wale bolts @ 2' above lower wale for fender system
 bolt heads in good condition

- no lower fender wale Sta 0+20 to 0+30
 studs for fastening broken off

Sta 0+40 to Sta 1+72.5 lower fender wale missing

- Sta 1+00 LII

② ML Red coating visible - good condition
 Primer ↑ 75% intact, steel smooth - good condition

Mid - same as ML

MLW - same as below

corrosion by-product on exposed steel w/ 1/8" max. pitting

alot of fishing debris on bottom

Sta 1+1/2 vertical fender loose

↑ typical timbers in good condition underwater
 above tidal zone ≈ 1" wearing

1+55 vertical fender broken, studs broken



CHILDS ENGINEERING CORPORATION

Waterfront and Structural Engineering

BOX 333, MEDFIELD, MA 02052

JOB _____

SHEET NO. _____

OF _____

CALCULATED BY _____

DATE _____

CHECKED BY _____

DATE _____

SCALE _____

Sta 1+67 ladder has no rungs below low wale
not connected below wale

Timber corner dolphin - 7 timber piles Sta 1+72.5
55 wire rope loose & on ML - was @ low wale
2 wraps at 4' below deck & 8' below
deck good condition
- sheet pile wale bolts - appear in good condition

Sta 2+00 black coating w/ Red primer @ ML
Steel good cond.
Mid-coated steel w/ primer - steel good

MLW - outer fl has $1\frac{1}{2}$ " ϕ hole w/ bolt, 1' below wale.
Steel wavy $\frac{1}{8}$ " w/ $\frac{1}{8}$ " by-product,
most coating missing - 80% missing

U/W Props #1-2 Outer fl - bolt hole w/ bolt MLW
#3 - Inner fl
#4, 5, 6 Mid + Outer fl & Web
#7, 8, 9, 10 @ ML inner & outer fl.

Sta 2+54 to 2+80 lower fender wale miss, w/ bolts missing

Sta 2+53 vert. fender base, top 3' abraded 2"
only attached @ top

Sta 2+72 vert. fender base only attached @ top



CHILDS ENGINEERING CORPORATION

Waterfront and Structural Engineering

BOX 333, MEDFIELD, MA 02052

JOB _____

SHEET NO. 3 OF _____

CALCULATED BY _____ DATE _____

CHECKED BY _____ DATE _____

SCALE _____

Sta 3+00 LII

Steel coated - black + red primer -

@ ML 60% coating intact - steel smooth good cond.

Mid same as ML

MLW - 1 1/2" p batt hole Steel around hole good

- steel

coating 30% intact black coating

Red primer intact

Red primer typically intact

Sta 4+05 LIII Steel in good condition - Black coating 60% intact
Red primer - 30% intact

U/W PHOTO 3 PHOTOS @ MLW #11, #2, #3

@ mid #14-16

@ ML #17, #18

Ladder @ 4+15 - no lower rungs. Bottom 4 rungs missing.

Diver out 12:05

MOVE STATION

Diver in 13:05

Sta 4+48 Vert fender piece loose no lower walk @ Sta 4+15 to 5+98

Sta 4+56 Vert fender loose 2 bottom bolts/studs missing

Sta 4+75 loose vert. fender bottom 2 stud miss. Rubbing on steel

4+84 " Coating miss

4+93 "



CHILDS ENGINEERING CORPORATION

Waterfront and Structural Engineering

BOX 333, MEDFIELD, MA 02052

JOB _____

SHEET NO. 4 OF _____

CALCULATED BY _____ DATE _____

CHECKED BY _____ DATE _____

SCALE _____

Sta 5+00 LIII

• ML - typical - black coating 60% intact
Red primer 30% intact steel good condition

• Mid - same as ML

• MLW - same as ML

• above MLW steel wavy, pits $\frac{1}{8}$ " deep max x $\frac{1}{2}$ " ϕ max

• sheet pile bolts - good condition - ~~coating same as ML~~

Sta 5+00 to 5+08 - fender system missing

Sta 5+02 $1\frac{1}{2}$ " hole in sheet @ low fender wale
fill visible behind

Sta 5+08

Corner dolphin - Top wrap attached other wraps, ~~2~~ ^{below} are
8 tricer piles loose w/ only 2 wraps left
out of 37 wraps / wrap

Sta 5+27 vert. fender base, bottom 2 studs/bolts missing

Sta 5+50 - same as 5+27, bottom of fender wearing into
sheetpile coating

Sta 6+00 Black coating 75% intact - steel good
LIII Primer - good 90% intact

L/W Photos #19 & #20 Inner + Outer fl. ML
#21 + 22 @ mid -
23, 24, 25 @ MLW inner, web, outer fl.



CHILDS ENGINEERING CORPORATION

Waterfront and Structural Engineering

BOX 333, MEDFIELD, MA 02052

JOB _____

SHEET NO. 5 OF _____

CALCULATED BY _____ DATE _____

CHECKED BY _____ DATE _____

SCALE _____

- Because of boat impact lower fender walls down
Sta 6+00 to 4+50

Sta 6+50 to 7+50 lower fender wall missing

~~Steel @ 6+50~~

Steel in tidal zone - no coating
pitted $\frac{1}{8}$ " - $\frac{1}{4}$ " deep x $\frac{1}{2}$ "
steel surface wavy

Sta 6+75 2 sheets w/ calcium deposits - @ 8' below lower fender wall
to mudline

ladder @ 6+98 missing bottom 3 Rungs

Sta 7+00 Level II

@ ML steel smooth 80% red primer intact
50% black coating intact

Mid-height - same

MLW - same w/ 40% black coating intact

Sta 8+00

steel good same condition as before w/ coating + smooth steel

Sta 7+98 - 8+08 lower fender wall missing

Sta 8+27 to 8+37 lower fender wall missing

Sta 8+86 $\frac{1}{4}$ - $\frac{3}{8}$ " of corrosion by-product water \approx 8' deep from wall

Diver Out 15:00



CHILDS ENGINEERING CORPORATION

Waterfront and Structural Engineering

BOX 333, MEDFIELD, MA 02052

JOB _____

SHEET NO. _____ OF _____

CALCULATED BY _____ DATE _____

CHECKED BY _____ DATE _____

SCALE _____

Driv in @ 1530
Sta 9+00 LIII

Steel & coating same as earlier - good steel
calcium build-up on sheets $\frac{1}{8}$ " thick

lower wall being - lost 12" hollow & split

9+05 - low high wall hollow 24"

9+14 - low high wall hollow 12"

3 pile cluster on corner - no wire wrap, banded @ top
piles in good condition

Sta 9+16 - low high wall bolt hole elongated to 4" ϕ
due to marine borers or abrasion

Sta 9+55 low high wall severely deteriorated due to
to 9+75 marine borers $\pm 50\%$ section missing

Sta 9+55 low high wall 2' marine borer damage - hollow at end

Sta 10+00 LIII ML to MLW $\approx 4'$

Driv Out 16:10

see Field Book #288 Page 15 for notes

Sta 10+00 to Sta. 11+21