Project:	Marion Project	Date: 3/20/91
TP-1		Investigator: R. Chlanda
<u>Depth</u>	Elev.	Soil Description
0.0-3.0	7.2-4.2	<pre>Dredged Fill, Sand, Poorly Graded, coarse to medium w/shells, less than 5% non-plastic fines, <5% gravel, lt. brown, loose. (SP)</pre>
3.0-3.5	4.2-3.7	Organic soil, w/sand about 20% fine sand, swamp, marsh deposit, soft. (OL)
3.5-4.3	3.7-2.9	<pre>Fat Clay, highly plastic, marine, soft, gray. (CH)</pre>
4.3-5.7	2.9-1.5	<pre>Peat w/fibrous roots and organics which give some strength, soft, black. (Pt)</pre>
5.7-8.0	1.5-(-0.8)	<pre>Sandy silt, non-plastic, w/40-45% fine sand, compact, gray-green. (ML)</pre>
8.0-10.0	(-0.8)-(-2.8)	Glacial Till, poorly graded sand w/silt, 10% non-plastic fines, gray brown. (SP-SM)
10.0	(-2.8)	Bottom of pit. 10.0.

(-) Below MSL

Project:	Marion Projec	Date: 3/20/91
TP-2		Investigator: R. Chlanda
<u>Depth</u>	Elev.	Soil Description
0.0-3.0	7.3-4.3	<pre>Dredged Fill, Poorly graded sand, coarse to medium, w/shells, less than 5% non-plastic fines, <5% gravel, lt. brown, loose. (SP)</pre>
3.0-4.0	4.3-3.3	Organic soil w/sand and Peat, about 5% v. fine sand, soft, swamp, marsh deposits. (OL) (PT)
4.0-6.0	3.3-1.3	<pre>Sandy silt, non-plastic w/40-45% v. fine sand, compact, gray. (ML)</pre>
6.0	1.3	Glacial till, poorly graded sand w/silt, coarse to fine, mostly medium, dense, light brown, 10-15% non-plastic fines. (SP-SM)
	Bottom of pi	it 6.0'.

Water table @ 3.0'.

Project: Marion Project Date: 3/20/91 TP-3 Investigator: R. Chlanda <u>Depth</u> Elev. Soil Description Dredged fill, Poorly graded sand, coarse to fine, mostly medium, w/shells, less than 5% non-plastic fines, loose lt. gray. (SP) 0.0-3.3 7.2-3.9 Peat, w about 5% fine sand, soft, fibrous,
marsh deposits. (Pt) 3.3-4.5 3.9-2.7 Poorly graded sand, mostly medium, light brown, w less than 5% non-plastic fines, loose. (SP) 4.5-6.0 2.7-1.2 6.0-7.6

1.2-(-0.4) Glacial Till, poorly graded sand w/silt, coarse to fine, mostly medium, light brown, with 10-15% non-plastic fines. (SP-SM) Bottom of pit 7.6'. 7.6 -(0.4)(-)Below sea level.

> SPRAGUES COVE / FRONT STREET STORMWATER REMEDIATION PROJECT MARION, MASSACHUSETTS

LOG OF TEST PITS

U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE

Investigated R. CHLANDA P. SEAVER Checked C.J. GUSTAFSON 5/93 No 5 of 6