



4. View of sheening and floating particulate oil that infiltrated into trenches and in raked areas. The oil was removed using oil-absorbent materials.