BOUCHARD B120 RELEASE SHORELINE SEGMENT SUMMARY



5 Lan Drive, Suite 200 Westford, Massachusetts 01886 Tel. (978) 692-1114 Fax (978) 692-1115

GeoInsight Project Number 3871-002

SEGMENT IDENTIFICATION: W1C-05

SEGMENT NAME: Sippican Harbor East

SEGMENT LOCATION: Marion, Massachusetts (Map attached)

MAXIMUM DEGREE OF INITIAL OILING: Moderate (Oiling Score: 3.00)

SEGMENT INSPECTION STATUS: Passed IRAC inspection on 08/07/2003.

SITE-SPECIFIC INFORMATION

PHYSICAL CHARACTERISTICS:

Primary Shoreline Type/ Geology:

• 1D: Rip rap seawalls, bulkheads, piers, docks, and pilings.

Secondary Shoreline Type/ Geology:

- 1B: Less utilized, semi-public and private sand beaches;
- 1C: Mixed sand and gravel, gravel (pebble to boulder), and rip rap groins (jetties); and
- 1F: Salt marshes.

Hvdrogeology:

 Sippican Harbor is located to the west, Hammetts Cove to the northwest, and Planting Island Cove and Buzzards Bay to the southeast.

Bedrock Geology:

 Bedrock underlying this segment is identified as undivided granite, gneiss, and schist (Zen, 1983).

ENVIRONMENTAL SENSITIVE RECEPTORS (Identified within 500 feet of segment):

Aquifer: None at segment.

Protected Open Space: At segment.

Public Ground Water Supply Wells: None at segment. Public Surface Water Supply Wells: None at segment.

Areas of Critical Environmental Concern (ACEC): None at segment.

Vernal Pools: None at segment.

Priority Habitats of Rare Species: At segment and adjacent to segment: Buzzards Bay aquatic environment.

Estimated Habitats of Rare Wildlife: At segment and adjacent to segment: Buzzards Bay aquatic environment.

Floodplains: At segment: 100-year floodplain.

HUMAN SENSITIVE RECEPTORS (Identified within 500 feet of segment):

<u>Segment Use</u>: Based upon inspections conducted under Unified Command, the segment appears to be a private and semi-public area. Residential dwellings are located within 500 feet of the segment. Portion of the segment appears to be accessible via roadway.

<u>Frequency of Use</u>: Presumed to be seasonal and year round residential use.

SUMMARY OF INSPECTION ACTIVITIES

WRF INSPECTIONS

(Wildlife Field Reconnaissance- Shoreline or On-Water Observations; Bird Transect Study.)

WRF inspections pertaining to this segment were not conducted.

NRDA FIELD ACTIVITIES SUMMARY

(Natural Resource Damage Assessment)

Note: Includes Shoreline Cleanup Assessment Team (SCAT) inspections and activities. SCAT forms were completed by field inspection teams working under the direction of Unified Command.

NRDA and SCAT inspections pertaining to this segment were not conducted.

IRAC INSPECTIONS


(Unified Command Immediate Response Action Completion inspections and activities.)

DATE	SUMMARY OF INFORMATION RECORDED BY INSPECTION TEAM
07/11/2003	Two oiled areas observed adjacent to a flagpole at Allen's Point Road. Segment did not meet
	IRAC criteria endpoints and further treatment was feasible. Additional cleanup activities were
	warranted.
08/07/2003	Three large oiled areas sheltered within the seawall were observed at the end of Allen's Point
	Road. The oil was not easily accessible, therefore natural attenuation was recommended for
	these areas. These oiled areas were considered to be inaccessible. Tarballs on small private sand
	beaches near Foster's Beach were observed. Segment met IRAC criteria endpoints with the
	condition that inspections and removal of tarballs continue on Foster's Beach.


MCP FIELD ACTIVITIES SUMMARY

(Massachusetts Contingency Plan inspections and activities under the direction of the Licensed Site Professional-of-Record.)

MCP inspections pertaining to this segment were not conducted. GeoInsight did not receive IRA citizen calls pertaining to this segment.



NATURAL HERITAGE AND ENDANGERED SPECIES MAP




LEGEND

NHESP 2005 MA PRIORITY
HABITATS FOR STATE-PROTECTED
RARE SPECIES

NHESP 2005 MA ESTIMATED HABITATS OF RARE WILDLIFE

2IE PRIORITY RESOURCE MAP





TOPOGRAPHIC MAP

