



1. Initial activities focused on the area surrounding $N41^{\circ}37.714$, $W70^{\circ}49.432$ on the east side of the Leisure Shores Beach, and then continued by following the tide line.



2. A total of approximately 180 x 80 foot area was raked and inspected in the intertidal zone at Leisure Shores.



3. Cleanup crew raking intertidal zone at Leisure Shores.